

Inspection Report

Report No.: XYDA-150312
 Supplier : XY-GLOBAL

Inspection Date: 5th Apr, 2015
 Inspector: Leo

Inspection only for: PO . XYDA-150312 Item No. XY31CY030	Inspection Result: PASS
---	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY030	35000PCS	1% inspection	0pcs	No failure	35000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing	2. Product
3. Product	4 Product
	深圳市真朴电子科技有限公司 XY Electronics Technology Co.,Ltd Inspection Report Form 检验报告单 品名: XY31CY030 规格: 1.0mm 数量: 35000 日期: 2015.04.05 检验员: Leo 审核员: Leo 批准: Leo 检验结果: PASS 检验日期: 2015.04.05 检验地点: 深圳 检验设备: 游标卡尺 检验方法: 目视 检验标准: 图纸 检验依据: 图纸 检验结论: 合格 检验员: Leo 审核员: Leo 批准: Leo
5. Product:	6. report

