

Inspection Report

Report No.: XYFD-130804

Inspection Date: 3th Sep-, 2013

Supplier: XY-GLOBAL

Inspector: LEO

Inspection only for: PO . XYFD-130804	Item No. 400-10-071	Inspection Result: PASS
--	---------------------	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-10-071	6000Set	100% inspection	0pcs	No failure	6000Set

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product :

[illegible]