

**Inspection Report**

**Report No.:** XYFD-130804  
**Supplier :** XY-GLOBAL

**Inspection Date:** 3<sup>th</sup> Sep-, 2013  
**Inspector:** LEO

Inspection only for: PO . XYFD-130804    Item No.400-10-071	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-10-071	6000Set	100% inspection	0pcs	No failure	6000Set

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product :

