

**Inspection Report**








Report No.: XYDA-150318  
 Supplier : XY-GLOBAL

Inspection Date: 10<sup>th</sup> Apr, 2015  
 Inspector: Leo

Inspection only for: PO . XYDA-150318 Item No. XY31CY035	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY035	30000PCS	1% inspection	0pcs	No failure	30000pcs

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	 深圳市真朴电子科技有限公司 XY Electronics Technology Co.,Ltd 
5. Product:	6. report

