

**Inspection Report**

Report No.: XYDA-150317  
 Supplier : XY-GLOBAL

Inspection Date: 10<sup>th</sup> Apr, 2015  
 Inspector: Leo

Inspection only for: PO . XYDA-150317 Item No. XY31CY034	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31CY034	30000PCS	1% inspection	0pcs	No failure	30000pcs








**Appearance Inspection :**  
 No failure,

**Dimension Inspection:**  
 No failure , below measurement report for reference.

**Assembly Test:**  
 No failure

**Inspection Summary**  
 The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	 深圳市真朴电子科技有限公司 XY Electronics Technology Co.,Ltd 
5. Product:	6. report

