



Inspection Report

Report No.: XYA-131021  
 Supplier : XY-GLOBAL

Inspection Date:15<sup>th</sup> Nov-, 2013  
 Inspector:ALEX

Inspection only for: PO . XYA-131021 Item No.XY-CT-D-070	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-CT-D-065	5000PCS	1% inspection	0pcs	No failure	5000pcs

**Appearance Inspection :**

No failure,

**Dimension Inspection:**

No failure , below measurement report for reference.

**Assembly Test:**

No failure

**Inspection Summary**

The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

