

Inspection Report

Report No.: XYKB-140517
 Supplier : XY-GLOBAL

Inspection Date: 12th Jun, 2014
 Inspector: Leo

Inspection only for: PO . XYKB-140517 Item No. XY72YM013	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM013	5000PCS	1% inspection	0pcs	No failure	5000pcs








Appearance Inspection :
 No failure,

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing 	2. Product 
3. Product 	4 Product  
5. Product:	6. Dimensions report:

