

**Inspection Report**







**Report No.:** XYDS-140607  
**Supplier :** XY-GLOBAL

**Inspection Date:** 11<sup>th</sup> July, 2014  
**Inspector:** Leo

Inspection only for: PO . XYDS-140607 Item No.100-50-300	<u>Inspection Result:</u> PASS
-------------------------------------------------------------	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
100-50-300	5000PCS	1% inspection	0pcs	No failure	5000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product

品名	CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
仕様	
数量	
単位	
公差	
表面処理	
検査	
納期	
備考	
寸法	+/-0.01
重量	50g以内
公差	
単位	
重量	50g以内 25g以内
公差	
1. CNC加工品	
2. 加工品	
AL6061 AL6065 AL6063 AL7075	
4. 公差	
5. 公差 ±0.01	
6. 重量 100g以内	
7. 公差	
8. 重量 25-30g	
9. 公差	
10. 公差	
11. ISO 9001	
ISO	
1.10 ISO	
2. 公差	
3. 公差	
4. 公差	
5. 公差	
6. 公差	
7. 公差	
ISO	
公差	
公差	
ISO9001	
公差	
OEM	