

Inspection Report

Report No.: XYSJ-140713
Supplier : XY-GLOBAL

Inspection Date: 17th Aug, 2014
Inspector: Leo

Inspection only for: PO . XYSJ-140713 Item No. XY11KA009	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11KA009	20000PCS	5% inspection	0pcs	No failure	20000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

--	--

1. Packing	2. Product

3. Product	4 Product

5. Product:	6. The test report
-------------	--------------------

說明	此表格係根據客戶需求，由本公司自行設計之OEM規格所製成
零件	ADC12(A380)
材料	不銹鋼
規格	符合ANSI B18.15.1之規格
表面	拋光
公差	±0.01mm
檢驗	依據ANSI Z39.50及MIL-STD-1916C之規格
包裝	每盒10個
單位	盒
檢驗	全檢
材料	5052 Al (5052)
規格	符合ANSI B18.15.1之規格
表面	拋光
公差	±0.01mm
檢驗	依據ANSI Z39.50及MIL-STD-1916C之規格
包裝	每盒10個
1. 零件說明	
2. 零件說明	
3. 零件規格 ADC12(A380)	
4. 零件說明	
5. 零件公差 ±0.01mm	
6. 零件規格 100mm	
7. 零件說明	
8. 零件規格 25-30mm	
9. 零件說明	
10. 零件說明	
11. 零件規格 ISO 9001	
說明	
1.10 零件規格 ISO	
2. 零件說明	
3. 零件說明	
4. 零件說明	
5. 零件	
6. 零件	
7. 零件說明	
說明	
零件說明	
零件說明	
零件規格 ISO9001	
零件說明	
零件說明	

Safety is our serious job for our worker and engineer team

