

Inspection Report







Report No.: XYK-140512
Supplier : XY-GLOBAL

Inspection Date: 9th Jun, 2014
Inspector: Ken

Inspection only for: PO . XYK-140512 Item No.XY-140347	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-140347	30000PCS	1% inspection	0pcs	No failure	30000pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Report:

品名	ADC12 A380 OEM
品番	ADC12 A380
仕様	
数量	
単位	
材質	
公差	+/-0.01
表面処理	T / T 50
検査	
包装	
納期	
備考	
1.Name	
2.Process	
品名	ADC12 A380
4.公差	
5.Tolerance	±0.01
6.数量	100
7.Specification	serice
8.納期	25-30
9.付属品	accessoried
10	Austria
11	ISO 9001
品名	
1	ISO
2	
3	kindls available
4	
5	
6	
7	
品名	
品名	NBSP
品名	
品名	ISO9001
品名	
品名	OEM