

6061□□□□



Inspection Report

Report No.: XYK-130803
Supplier : XY-GLOBAL







Inspection Date:06th- Sep-, 2013
Inspector:LEO

Inspection only for: PO . XYK-130803 Item No.1305970	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1300098	2000PCS	3% inspection	0pcs	No failure	2000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

品名	铝合金 CNC 加工零件 CNC 加工
材料	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	零件
数量	零件
公差	±0.01
表面处理	阳极氧化
检验标准	ISO 9001
交货期	10 天
包装	泡沫包装
备注	
1.Name	铝合金 CNC 加工
2.Process	CNC 加工
	AL6061 AL6065 AL6063 AL7075
4.	
5.Tolerance	±0.01
6.	100 件
7.Specification	serice
8.	25-30 天
9.	accessoried
10.	Austrial
11&NBSP;	ISO 9001
品名	
1.	10 天 ISO
2.	
3.	kindls available
4.	
5.	
6.	
7.	
品名	
	&NBSP; 零件
	ISO 9001