

**Inspection Report**

Report No.: XYLA-150305  
 Supplier : XY-GLOBAL


Inspection Date: 10<sup>th</sup> Apr, 2015  
 Inspector: Leo

Inspection only for: PO . XYLA-150305 Item No. XY31PC004	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC004	20000PCS	1% inspection	0pcs	No failure	20000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report



Safety is our serious job for our worker and engineer team

