

**Inspection Report**







Report No.: XYFA-130802  
 Supplier : XY-GLOBAL

Inspection Date: 1<sup>st</sup> Sep-, 2013  
 Inspector: LEO

Inspection only for: PO . XYFA-130802      Item No.400-01-056	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-01-056	100000pcs	100% inspection	0pcs	No failure	100000pcs

<b>Appearance Inspection :</b> No failure.
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product :

