

Inspection Report

Report No.: XYSL-150718
 Supplier : XY-GLOBAL







Inspection Date: 22th Aug, 2015
 Inspector: Leo

Inspection only for: PO . XYSL-150718 Item No. XY31XL038	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL038	8000PCS	1% inspection	Opcs	No failure	8000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

Safety is our serious job for our worker and engineer team

