

□□□□□□□□

Inspection Report

Report No.: XYS-130314
 Supplier : XY-GLOBAL

Inspection Date: 14th Apr, 2013
 Inspector: Leo

| | |
|--|-----------------------------------|
| Inspection only for: PO . XYS-130314 Item No.XY-1315400 | <u>Inspection Result:</u> PASS |
|--|-----------------------------------|

| Description | Finished Q'ty | Sample Size | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|----------------|--------------|---------------------|-----------------|
| XY-1315400 | 300PCS | 10% inspection | 0pcs | No failure | 300pcs |

| |
|--|
| Appearance Inspection : |
| No failure, |
| Dimension Inspection: |
| No failure , below measurement report for reference. |
| Assembly Test: |
| No failure |
| Inspection Summary |
| The inspection sample plan is 100% inspection. |

Digital photo records :

| | |
|---|--|
|  |  |
| 1. Packing | 2. Product |
|  |  |
| 3. Product | 4 Product |
|  |  |
| 5. Product: | 6. Product: |

| | |
|-----------------|------------------|
| 品名 | ADC12 A380 OEM |
| 品番 | ADC12 A380 |
| 仕様 | |
| 数量 | |
| 単位 | |
| 材質 | ADC12 A380 |
| 公差 | +/-0.01 |
| 表面処理 | T / T 50 |
| 検査 | ISO 9001 |
| 納期 | 20-25 日 |
| 備考 | |
| 1.Name | ADC12 A380 |
| 2.Process | |
| 3.品番 | ADC12 A380 |
| 4.公差 | +/-0.01 |
| 5.Tolerance | +/-0.01 |
| 6.表面処理 | T / T 50 |
| 7.Specification | ISO 9001 |
| 8.納期 | 20-25 日 |
| 9.検査 | ISO 9001 |
| 10.備考 | |
| 11.&NBSP; | ISO 9001 |
| 品名 | |
| 1.品番 | ISO 9001 |
| 2.仕様 | |
| 3.種類 | kindls available |
| 4.数量 | |
| 5.単位 | |
| 6.材質 | |
| 7.表面処理 | |
| 品名 | |
| 品番 | ISO 9001 |
| 仕様 | |
| 数量 | |
| 単位 | |
| 備考 | OEM |