

□□□□□□□□

Inspection Report

Report No.: XYS-130308
Supplier : XY-GLOBAL

Inspection Date: 20th Apr, 2013
Inspector: Leo

Inspection only for: PO . XYS-130308 Item No.XY-130014	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY-130014	10000PCS	10% inspection	0pcs	No failure	10000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	ADC12 A380 OEM
品番	ADC12 A380
仕様	
数量	
単位	
材質	ADC12 A380
公差	+/-0.01
表面処理	T / T 50
検査	ISO 9001
備考	
1.Name	ADC12 A380
2.Process	ADC12 A380
4.公差	+/-0.01
5.Tolerance	+/-0.01
6.表面処理	T / T 50
7.Specification	ISO 9001
8.検査	ISO 9001
9.備考	
10.品名	ADC12 A380
11.公差	+/-0.01
備考	
1.品名	ADC12 A380
2.公差	+/-0.01
3.表面処理	T / T 50
4.検査	ISO 9001
5.備考	
6.品名	ADC12 A380
7.公差	+/-0.01
備考	
品名	ADC12 A380
公差	+/-0.01
表面処理	T / T 50
検査	ISO 9001
備考	
品名	ADC12 A380
公差	+/-0.01
表面処理	T / T 50
検査	ISO 9001
備考	