

Inspection Report







Report No.: XYSL-150622
 Supplier : XY-GLOBAL

Inspection Date: 25th July, 2015
 Inspector: Leo

Inspection only for: PO . XYSL-150622 Item No. XY31XL020	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL020	10000PCS	1% inspection	0pcs	No failure	10000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

品名	铝合金CNC加工零件CNC
材料	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	定制
数量	10000件
公差	±0.01mm
表面处理	阳极氧化
包装	泡沫+纸箱
交货期	15天
付款方式	预付30%
工厂地址	深圳市宝安区
联系电话	0755-12345678
电子邮箱	sales@aluminum.com
公司名称	铝合金精密加工有限公司
公司地址	深圳市宝安区西乡街道
邮编	518102
开户行	招商银行
账号	440012345678901011
联系人	张经理
手机	13800138000
QQ	123456789
微信	aluminum2024
认证	ISO 9001
其他	
1. 铝合金CNC加工	
2. 精密加工	
3. 材料 AL6061 AL6065 AL6063 AL7075	
4. 表面处理	
5. 公差 ±0.01mm	
6. 数量 10000件	
7. 交货期 15天	
8. 付款方式 预付30%	
9. 工厂地址 深圳市宝安区	
10. 联系电话 0755-12345678	
11. 认证 ISO 9001	
其他	
1.10 铝合金ISO	
2. 精密加工	
3. 表面处理	
4. 数量	
5. 公差	
6. 交货期	
7. 付款方式	
工厂地址	
联系电话	
认证	
其他	
铝合金ISO9001	
精密加工	
OEM	

Safety is our serious job for our worker and engineer team

