

Inspection Report

Report No.: XYA-130810
Supplier : XY-GLOBAL

Inspection Date:11th Sep-, 2013
Inspector:LEO

Inspection only for: PO . XYA-130810 Item No.130014	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
130014	5000PCS	3% inspection	0pcs	No failure	5000pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing



2. Product:



3. Product:



4. Product:



5. Product :



6. Product:

