

Inspection Report

Report No.: XYLA-150410
 Supplier : XY-GLOBAL

Inspection Date: 18th May, 2015
 Inspector: Leo

Inspection only for: PO . XYLA-150410 Item No. XY31PC020	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC020	35000PCS	1% inspection	0pcs	No failure	35000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

0000	0000000CNC0000000000000000CNC00
00	000 AL6061 AL60650AL60630AL70750SUS3040SUS3030SUS3160
00	00000000
0000	0000000000000000000000000000
00	0000000000
0000	00000000000000000000000000000000 0000
0000	00
000000	00000000
00/00	+/-0.0100
0000	00000500
0000	00
00	00
00	000000
00	0000000500000000250000
0000	00000000
1.0000000000CNC00	
2.000000000000000000	
0000000AL6061 AL60650AL60630AL70750	
4.00000000000000000000 0000	
5.0000000±0.0100	
6.000000100000	
7.0000000000000000000000000000	
8.00000025-3000	
9.00000000000000000000 0000000000000000	
10.0000000000000000000000	
11000000000ISO 9001	
000000	
1.10000000ISO00	
2.000000000000000000	
3.000000000000000000	
4.000000000000	
5.000000	
6.000000	
7.00000000000000	
000000	
000000000000000000000000	
0000000000000000	
00000000000ISO9001	
00000000000000000000	
00OEM00000000	



High qualified surface treatment can make your parts perfect !!!

