

**Inspection Report**

**Report No.:** XYNK-140623  
**Supplier :** XY-GLOBAL

**Inspection Date:** 19<sup>th</sup> July, 2014  
**Inspector:** Leo

Inspection only for: PO . XYNK-140623 Item No.1300083	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1300083	3000PCS	1% inspection	0pcs	No failure	3000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

