

**Inspection Report**

Report No.: XYKS-140610  
Supplier : XY-GLOBAL

Inspection Date: 5<sup>th</sup> July, 2014  
Inspector: Leo

Inspection only for: PO . XYSK-140610 Item No. XY31SY54	Inspection Result: PASS
--	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY54	12000PCS	1% inspection	0pcs	No failure	12000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

材质	铝合金CNC加工不锈钢CNC
规格	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
重量	可定制
公差	±0.05mm
表面	可定制
颜色	可定制
厚度	可定制
长度	可定制
直径	可定制
价格	根据数量和规格
交货	可定制
包装	可定制
认证	ISO 9001
工厂	自有工厂
服务	提供技术支持
地址	广东东莞
电话	+86 769 8888 8888
邮箱	sales@aluminum.com.cn
网址	www.aluminum.com.cn
行业	机械 航空 航海 汽车
应用	各种精密零件
优势	价格公道 质量可靠 交货及时
合作	欢迎各界人士垂询

Safety is our serious job for our worker and engineer team

