

**Inspection Report**

**Report No.:** XYF-130803  
**Supplier :** XY-GLOBAL

**Inspection Date:** 1<sup>th</sup> Sep-, 2013  
**Inspector:** LEO

<b>Inspection only for:</b> PO . XYK-130803      Item No.100-23-690	<b>Inspection Result:</b> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
100-23-690	<b>30000Set</b>	100% inspection	0pcs	No failure	30000Set

<b>Appearance Inspection :</b> No failure,
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :



1. Packing      2. Product.



3. Product:      4. Product:



5. Product :      6. inspection reports

