



Inspection Report

Report No.: XYF-130811  
 Supplier : XY-GLOBAL

Inspection Date: 5<sup>th</sup> Sep, 2013  
 Inspector: LEO

Inspection only for: PO . XYF-130811      Item No.300276	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
300276	10000Set	100% inspection	0pcs	No failure	10000Set

**Appearance Inspection :**  
 No failure.

**Dimension Inspection:**  
 No failure , below measurement report for reference.

**Assembly Test:**  
 No failure

**Inspection Summary**  
 The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing	2. Product
3. Product:	4. Product:
5. Product :	6. inspection reports

