

Inspection Report

Report No.: XYBA-141113
Supplier : XY-GLOBAL

Inspection Date: 12th Dec-, 2014
Inspector:LEO

Inspection only for: PO : XYBA-141113 Item No. XY21ZC034	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC034	10000Pcs	7% inspection	0pcs	No failure	10000Pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

11

品名	铝合金CNC加工件CNC件
材料	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
规格	定制
数量	10000件
单位	件
重量	约100kg
尺寸	长100mm 宽50mm 高20mm
表面处理	阳极氧化 喷砂 电泳 电镀
包装	泡沫箱+气泡膜+木架
交货期	15天
公差	±0.01mm
最小起订量	500件
最大起订量	50000件
付款方式	预付30% 货到付清
交货地点	工厂
联系人	王经理
电话	13800000000
地址	深圳市宝安区西乡街道

1. 1. CNC

2.

AL6061 AL6065 AL6063 AL7075

4. □□□□□□□□□□□□□□□□ □□□□

5.□□□□□□±0.01□□

6. 100

7.

8. 25-30

9. □□□□□□□□□□□□□□ □□□□□□□□□□□□

10.

11 □ □ □ □ □ □ □ □ ISO 9001

--	--	--	--	--

1.10

2.

3. □□□□□□□□□□□□□□

[illegible]

5.□□□□□

6. □□□□□□

7.

--	--	--	--	--

[illegible][illegible]

□□□□□□□□□□ISO9001

[illegible]

□□OEM□□□□□□