

Inspection Report

Report No.: XYDN-140623
 Supplier : XY-GLOBAL

Inspection Date: 20th July, 2014
 Inspector: Leo

Inspection only for: PO . XYDN-140623 Item No.4010358	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
4010358	2000PCS	1% inspection	0pcs	No failure	2000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product

項目	項目名CNC加工品CNC加工品
材料	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	形状
仕様	仕様
公差	公差
表面処理	表面処理
検査	検査
包装	包装
納期	納期
価格	価格
MOQ	+/-0.01
ロット	ロット50ロット
ロット	ロット50ロット25ロット
ロット	ロット
1.項目名CNC加工品	
2.項目名	
項目名AL6061 AL6065 AL6063 AL7075	
4.項目名	
5.項目名±0.01	
6.項目名100	
7.項目名	
8.項目名25-30	
9.項目名	
10.項目名	
11項目名ISO 9001	
項目名	
1.10項目名ISO	
2.項目名	
3.項目名	
4.項目名	
5.項目名	
6.項目名	
7.項目名	
項目名	
項目名	
項目名	
項目名ISO9001	
項目名	
項目名	
項目名OEM	