

Inspection Report

Report No.: XYAN-150305
 Supplier : XY-GLOBAL

Inspection Date: 3rd Apr-, 2015
 Inspector: LEO

Inspection only for: PO . XYBA-150305 Item No. XY21ZC092	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC092	8000pcs	7% inspection	0pcs	No failure	8000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

品名	汎用CNC加工品汎用CNC
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	汎用加工品
用途	汎用加工品
仕様	汎用加工品
公差	±0.05mm
表面処理	汎用加工品
検査	汎用加工品
納期	汎用加工品
価格	汎用加工品
備考	汎用加工品
1. 汎用加工品CNC	
2. 汎用加工品	
汎用加工品AL6061 AL6065 AL6063 AL7075	
4. 汎用加工品	
5. 汎用加工品±0.01mm	
6. 汎用加工品100mm	
7. 汎用加工品	
8. 汎用加工品25-30mm	
9. 汎用加工品	
10. 汎用加工品	
11. 汎用加工品ISO 9001	
汎用加工品	
1.10 汎用加工品ISO	
2. 汎用加工品	
3. 汎用加工品	
4. 汎用加工品	
5. 汎用加工品	
6. 汎用加工品	
7. 汎用加工品	
汎用加工品	
汎用加工品	
汎用加工品	
汎用加工品ISO9001	
汎用加工品	
汎用加工品	
汎用OEM加工品	

Safety is our serious job for our worker and engineer team

