

Inspection Report

Report No.: XYNK-140624
 Supplier : XY-GLOBAL

Inspection Date: 19th July, 2014
 Inspector: Leo

Inspection only for: PO . XYNK-140624 Item No.130208	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
130208	2000PCS	1% inspection	0pcs	No failure	2000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

品名	機械加工CNC部品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
仕様	図面指定
数量	1000個
単位	個
公差	±0.05mm
表面処理	バリ取り
検査	目視検査
納期	発注後1週間
備考	
品名	機械加工CNC部品
材質	AL6061 AL6065 AL6063 AL7075
仕様	図面指定
数量	500個
単位	個
公差	±0.01mm
表面処理	バリ取り
検査	目視検査
納期	発注後1週間
備考	
1. 機械加工CNC部品	
2. 図面指定	
3. 材質AL6061 AL6065 AL6063 AL7075	
4. 公差±0.01mm	
5. 公差±0.01mm	
6. 公差100mm	
7. 公差指定	
8. 公差25-30mm	
9. 公差指定	
10. 公差指定	
11. 公差ISO 9001	
公差	
1.10公差ISO	
2. 公差指定	
3. 公差指定	
4. 公差指定	
5. 公差	
6. 公差	
7. 公差指定	
公差	
公差指定	
公差指定	
公差ISO9001	
公差指定	
公差OEM指定	