

Inspection Report

Report No.: XYDS-140629
Supplier : XY-GLOBAL

Inspection Date: 25th July, 2014
Inspector: Leo

Inspection only for: PO . XYDS-140629 Item No.903700	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
903700	8000PCS	1% inspection	0pcs	No failure	8000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product

品名	汎用CNC加工品汎用CNC
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	汎用加工品
用途	汎用加工品
公差	±0.01mm
表面処理	バリ取り
検査	寸法検査
納期	1週間程度
送料	別途見積
備考	
1.	汎用CNC加工
2.	汎用加工品
	AL6061 AL6065 AL6063 AL7075
4.	バリ取り
5.	±0.01mm
6.	100mm
7.	汎用加工品
8.	25-30mm
9.	汎用加工品
10.	汎用加工品
11.	ISO 9001
	汎用加工品
1.10.	ISO
2.	汎用加工品
3.	汎用加工品
4.	汎用加工品
5.	汎用加工品
6.	汎用加工品
7.	汎用加工品
	汎用加工品
	汎用加工品
	汎用加工品
	ISO9001
	汎用加工品
	汎用加工品
	OEM加工品