

Inspection Report



Report No.: XYKS-140611
 Supplier : XY-GLOBAL

Inspection Date: 5th July, 2014
 Inspector: Leo

Inspection only for: PO . XYSK-140611 Item No. XY31SY55	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY55	12000PCS	1% inspection	0pcs	No failure	12000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :																			
																			
1. Packing	2. Product																		
																			
3. Product	4 Product																		
	 深圳市真朴电子科技有限公司 XY Electronics Technology Co.,Ltd <table border="1"> <tr> <td>Client/Project</td> <td>XY31SY55</td> <td>Product Type</td> <td>XY31SY55</td> <td>Inspection Date</td> <td>2014.7.5</td> </tr> <tr> <td>Part No.</td> <td>XY31SY55</td> <td>Lot/Production Date</td> <td>2014.7.5</td> <td>Customer Name</td> <td>XY-GLOBAL</td> </tr> <tr> <td>Inspector</td> <td>Leo</td> <td>Inspector</td> <td>Leo</td> <td>Inspector</td> <td>Leo</td> </tr> </table>	Client/Project	XY31SY55	Product Type	XY31SY55	Inspection Date	2014.7.5	Part No.	XY31SY55	Lot/Production Date	2014.7.5	Customer Name	XY-GLOBAL	Inspector	Leo	Inspector	Leo	Inspector	Leo
Client/Project	XY31SY55	Product Type	XY31SY55	Inspection Date	2014.7.5														
Part No.	XY31SY55	Lot/Production Date	2014.7.5	Customer Name	XY-GLOBAL														
Inspector	Leo	Inspector	Leo	Inspector	Leo														
5. Product:	6. report																		

Safety is our serious job for our worker and engineer team

