

Inspection Report

Report No.: XYF-130821
Supplier : XY-GLOBAL

Inspection Date: 15th Sep, 2013
Inspector: LEO

Inspection only for: PO . XYF-130821 Item No. Abnornity nut	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
Abnornity nut	6000Set	100% inspection	0pcs	No failure	6000Set

Appearance Inspection :
 No failure.

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing	2. Product:
3. Product:	4. Product:
5. Product :	6. inspection reports

