

Inspection Report

Report No.: XYF-130804
 Supplier : XY-GLOBAL

Inspection Date: 1th Sep, 2013
 Inspector: LEO

Inspection only for: PO . XYK-130804 Item No.100-23-870	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
100-23-870	30000Set	100% inspection	0pcs	No failure	30000Set

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

1. Packing	2. Product:
3. Product:	4. Product:
5. Product :	6. inspection reports

項目	項目名CNC加工品CNC加工
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	各種形状
寸法	各種寸法
公差	各種公差
表面処理	各種表面処理
検査	各種検査
納期	各種納期
数量	各種数量
単位	個
公差	+/-0.01
寸法	最大50mm 最小50mm
形状	各種形状
寸法	各種寸法
公差	各種公差
単位	個
寸法	最大50mm 最小25mm
公差	各種公差
1. CNC加工	
2. 各種形状	
材質 AL6061 AL6065 AL6063 AL7075	
4. 各種表面処理	
5. 各種公差 ±0.01	
6. 各種寸法 100mm	
7. 各種形状	
8. 各種寸法 25-30mm	
9. 各種検査	
10. 各種納期	
11. ISO 9001	
項目名	
1.10 ISO	
2. 各種形状	
3. 各種寸法	
4. 各種形状	
5. 各種寸法	
6. 各種形状	
7. 各種寸法	
項目名	
各種形状	
各種寸法	
ISO9001	
各種検査	
OEM加工	