

Inspection Report

Report No.: XYLA-150403
 Supplier : XY-GLOBAL

Inspection Date: 7th May, 2015
 Inspector: Leo

Inspection only for: PO . XYLA-150403 Item No. XY31PC013	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC013	25000PCS	1% inspection	0pcs	No failure	25000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

品名	CNC加工品 CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
仕様	
数量	
単位	
公差	
表面処理	
検査	
納期	
梱包	
備考	
1. CNC加工品	
2. 加工品	
3. AL6061 AL6065 AL6063 AL7075	
4. 加工品	
5. 公差 ±0.01	
6. 100	
7. 加工品	
8. 25-30	
9. 加工品	
10. 加工品	
11. ISO 9001	
加工品	
1.10. ISO	
2. 加工品	
3. 加工品	
4. 加工品	
5. 加工品	
6. 加工品	
7. 加工品	
加工品	
加工品	
加工品	
ISO9001	
加工品	
OEM加工品	



High qualified surface treatment can make your parts perfect !!!

