

**Inspection Report**

Report No.: XYSK-140608  
Supplier : XY-GLOBAL

Inspection Date: 2<sup>th</sup> July, 2014  
Inspector: Leo

Inspection only for: PO . XYSK-140608 Item No. XY31SY008	Inspection Result: PASS
---	----------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31SY008	16000PCS	1% inspection	0pcs	No failure	15000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	 
5. Product:	6. report

