

Inspection Report

Report No.: XYLA-150318
 Supplier : XY-GLOBAL

Inspection Date: 18th Apr, 2015
 Inspector: Leo

Inspection only for: PO . XYLA-150318 Item No. XY31PC012	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC012	25000PCS	1% inspection	0pcs	No failure	25000pcs

Appearance Inspection :
No failure,
Dimension Inspection:
No failure , below measurement report for reference.
Assembly Test:
No failure
Inspection Summary
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

0000	00000000CNC0000000000000000CNC00
00	000 AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
00	00000000
0000	0000000000000000000000000000
00	0000000000
0000	00000000000000000000000000000000 0000
0000	0000000000000000000000 0000000000000000000000000000000000
000000	00000000
00/00	+/-0.0100
0000	00005000000000000000005000000
0000	000
00	000
00	00000
00	00000050000000250000
0000	00000000
1.0000000000CNC00	
2.000000000000000000	
000000AL6061 AL6065AL6063AL7075	
4.000000000000000000 0000	
5.000000±0.0100	
6.000000100000	
7.000000000000000000000000	
8.00000025-3000	
9.000000000000000000 0000000000000000	
10.0000000000000000000000	
110000000000ISO 9001	
000000	
1.1000000000ISO00	
2.000000000000000000	
3.000000000000000000	
4.000000000000	
5.000000	
6.000000	
7.0000000000000000	
000000	
000000000000000000000000	
0000000000000000	
000000000000ISO9001	
00000000000000000000	
00OEM00000000	

Safety is our serious job for our worker and engineer team

