

Inspection Report

Report No.: XYSJ-140704
 Supplier : XY-GLOBAL



Inspection Date: 1st Aug, 2014
 Inspector: Leo

Inspection only for: PO . XYSJ-140704 Item No. XY11KA002	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY11KA002	26000PCS	5% inspection	0pcs	No failure	26000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :



3. Product	4 Product

5. Product. 6. The test report

Safety is our serious job for our worker and engineer team

