

Inspection Report







Report No.: XYNK-130819  
 Supplier : XY-GLOBAL

Inspection Date: 15<sup>th</sup> Sep-, 2013  
 Inspector: LEO

Inspection only for: PO . XYNK-130819 Item No.1401200	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
1401200	1000PCS	100% inspection	0pcs	No failure	1000pcs

<b>Appearance Inspection :</b> No failure.
<b>Dimension Inspection:</b> No failure , below measurement report for reference.
<b>Assembly Test:</b> No failure
<b>Inspection Summary</b> The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

