

Inspection Report


Report No.: XYKB-140524
Supplier: XY-GLOBAL

Inspection Date: 20th Jun, 2014
Inspector: Leo

Inspection only for: PO . XYKB-140524 Item No. XY72YM020	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY72YM020	5000PCS	1% inspection	0pcs	No failure	5000pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :									
									
1. Packing	2. Product								
									
3. Product	4 Product								
	<p>XY-GLOBAL 深圳市真朴电子科技有限公司 XY Electronics Technology Co.,Ltd</p> <table border="1"> <tr> <td>Client: XYKB-140524</td> <td>Product Type: XY72YM020</td> <td>Inspection Date: 2014.06.20</td> <td>Inspector: Leo</td> </tr> <tr> <td>PO: XYKB-140524</td> <td>Lot: XY72YM020</td> <td>Customer Name: XY-GLOBAL</td> <td></td> </tr> </table> <p>Inspection Result: PASS</p> <p>Inspection Summary: No failure.</p> <p>Inspection Details: 100% inspection.</p> <p>Inspection Report: XY72YM020</p>	Client: XYKB-140524	Product Type: XY72YM020	Inspection Date: 2014.06.20	Inspector: Leo	PO: XYKB-140524	Lot: XY72YM020	Customer Name: XY-GLOBAL	
Client: XYKB-140524	Product Type: XY72YM020	Inspection Date: 2014.06.20	Inspector: Leo						
PO: XYKB-140524	Lot: XY72YM020	Customer Name: XY-GLOBAL							
5. Product:	6. Dimensions report:								

