

Inspection Report

Report No.: XYBA-141108
Supplier : XY-GLOBAL

Inspection Date: 7th Dec-, 2014
Inspector:LEO

Inspection only for: PO . XYBA-141108 Item No. XY21ZC025	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC025	3000pcs	7% inspection	0pcs	No failure	3000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

品名	標準品CNC加工品CNC加工品
材質	AL6061 AL6065AL6063AL7075SUS304SUS303SUS316
公差	標準公差
表面処理	標準表面処理
加工方法	標準加工方法
検査方法	標準検査方法
保管方法	標準保管方法
包装方法	標準包装方法
納期	標準納期
送料	標準送料
価格	標準価格
最小ロット	50個
最大ロット	50個
公差	+/-0.01
表面処理	標準表面処理
加工方法	標準加工方法
検査方法	標準検査方法
保管方法	標準保管方法
包装方法	標準包装方法
納期	標準納期
送料	標準送料
価格	標準価格
最小ロット	50個
最大ロット	25個
公差	標準公差
1. 標準品CNC加工品	
2. 標準品	
標準品AL6061 AL6065AL6063AL7075	
4. 標準品	
5. 標準品±0.01	
6. 標準品100	
7. 標準品	
8. 標準品25-30	
9. 標準品	
10. 標準品	
11. 標準品ISO 9001	
標準品	
1.10 標準品ISO	
2. 標準品	
3. 標準品	
4. 標準品	
5. 標準品	
6. 標準品	
7. 標準品	
標準品	
標準品	
標準品	
標準品ISO9001	
標準品	
標準品OEM	