

Inspection Report

Report No.: XYBA-141117
 Supplier : XY-GLOBAL

Inspection Date: 19th Dec-, 2014
 Inspector:LEO

Inspection only for: PO . XYBA-141117 Item No. XY21ZC037	<u>Inspection Result:</u> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC037	6000Pcs	7% inspection	0pcs	No failure	6000Pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

