

**Inspection Report**







Report No.: XYBA-141120  
 Supplier : XY-GLOBAL

Inspection Date: 19<sup>th</sup> Dec-, 2014  
 Inspector:LEO

|  |                                   |
|--|-----------------------------------|
| Inspection only for:<br>PO . XYBA-141120    Item No. XY21ZC039 | <u>Inspection Result:</u><br>PASS |
|--|-----------------------------------|

| Description | Finished Q'ty | Sample Size   | Defect Found | Defects Description | Acceptable Q'ty |
|-------------|---------------|---------------|--------------|---------------------|-----------------|
| XY21ZC039   | 5000Pcs       | 7% inspection | 0pcs         | No failure          | 6000Pcs         |

|  |
|--|
| <b>Appearance Inspection :</b><br>No failure,  |
| <b>Dimension Inspection:</b><br>No failure , below measurement report for reference. |
| <b>Assembly Test:</b><br>No failure  |
| <b>Inspection Summary</b><br>The inspection sample plan is 100% inspection.          |

|   |   |
|---|---|
| Digital photo records :   |   |
|   |   |
| 1. Packing  | 2. Product:   |
|  |  |
| 3. Product:   | 4. Product:   |
|  |  |
| 5. Product :  | 6. Inspection report:   |

