

**Inspection Report**



Report No.: XYLA-150412  
 Supplier : XY-GLOBAL

Inspection Date: 18<sup>th</sup> May, 2015  
 Inspector: Leo

Inspection only for: PO . XYLA-150412 Item No. XY31PC022	<b>Inspection Result:</b> PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31PC022	25000PCS	1% inspection	0pcs	No failure	25000pcs

<b>Appearance Inspection :</b>
No failure,
<b>Dimension Inspection:</b>
No failure , below measurement report for reference.
<b>Assembly Test:</b>
No failure
<b>Inspection Summary</b>
The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

品名	铝合金CNC加工零件CNC
材料	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	定制
数量	10000件
公差	±0.01mm
表面处理	阳极氧化
包装	泡沫+纸箱
交货期	15天
付款方式	预付30%
工厂地址	深圳市宝安区
联系电话	0755-12345678
电子邮箱	sales@aluminum.com
公司名称	铝合金加工厂
公司地址	深圳市宝安区西乡街道
公司邮编	518102
公司网站	www.aluminum.com
1. 铝合金CNC加工	
2. 铝合金零件	
材料AL6061 AL6065 AL6063 AL7075	
4. 公差±0.01mm	
5. 公差±0.01mm	
6. 公差100mm	
7. 公差0.01mm	
8. 公差25-30mm	
9. 公差0.01mm	
10. 公差0.01mm	
11. 符合ISO 9001	
工厂	
1.10 符合ISO	
2. 符合ISO	
3. 符合ISO	
4. 符合ISO	
5. 符合ISO	
6. 符合ISO	
7. 符合ISO	
工厂	
符合ISO9001	
符合ISO9001	
符合ISO9001	
OEM	



High qualified surface treatment can make your parts perfect !!!

