

Inspection Report

Report No.: XYBA-141127
 Supplier : XY-GLOBAL

Inspection Date: 24th Dec-, 2014
 Inspector:LEO

Inspection only for: PO . XYBA-141127 Item No. XY21ZC044	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC044	3000Pcs	7% inspection	0pcs	No failure	3000Pcs

Appearance Inspection :
 No failure,

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p>	<p>2. Product:</p>
	
<p>3. Product:</p>	<p>4. Product:</p>
	
<p>5. Product :</p>	<p>6. Inspection report:</p>

項目	内容
加工方法	数値制御(CNC)加工
材料	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
公差	±0.05mm
表面処理	表面研磨
加工精度	±0.01mm
加工速度	約50mm/min
加工時間	約25-30分
加工コスト	約100円
加工場所	東京都中央区
加工業者	株式会社ABC
加工設備	数値制御(CNC)加工機
加工工程	1. 材料の準備 2. 加工プログラムの作成 3. 加工機の設定 4. 加工の実行 5. 加工後の検査 6. 加工物の仕上げ
加工品質	高精度の加工が可能
加工実績	数多くの加工実績あり
加工保証	加工品質の保証あり
加工相談	お問い合わせください
加工お問い合わせ	TEL: 03-XXXX-XXXX
加工お問い合わせ	Eメール: info@abc.com
加工お問い合わせ	ウェブサイト: www.abc.com
加工お問い合わせ	ISO9001
加工お問い合わせ	品質保証
加工お問い合わせ	OEM加工