

Inspection Report

Report No.: XYBA-141111
 Supplier : XY-GLOBAL

Inspection Date: 12th Dec-, 2014
 Inspector:LEO

Inspection only for: PO . XYBA-141111 Item No. XY21ZC028	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC028	6000Pcs	7% inspection	0pcs	No failure	6000Pcs

Appearance Inspection :
 No failure.

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p> 	<p>2. Product:</p> 
<p>3. Product:</p> 	<p>4. Product:</p> 
<p>5. Product :</p>	<p>6. Inspection report:</p>

