

Inspection Report

Report No.: XYGA-150307
 Supplier : XY-GLOBAL

Inspection Date: 5th Apr., 2015
 Inspector: LEO

Inspection only for: PO . XYGA-140307 Item No. XY21ZC048	Inspection Result: PASS
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC048	3800pcs	7% inspection	0pcs	No failure	3800pcs

Appearance Inspection :
 No failure,

Dimension Inspection:
 No failure , below measurement report for reference.

Assembly Test:
 No failure

Inspection Summary
 The inspection sample plan is 100% inspection.

Digital photo records :

	
<p>1. Packing</p>	<p>2. Product:</p>
	
<p>3. Product:</p>	<p>4. Product:</p>
	
<p>5. Product :</p>	<p>6. Inspection report:</p>

品名	铝合金CNC加工零件CNC
材料	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	定制
数量	10000件
公差	±0.01mm
表面处理	阳极氧化
包装	泡沫箱+纸箱
交货期	15天
付款方式	预付30%
工厂地址	深圳市宝安区
联系电话	0755-12345678
电子邮箱	sales@aluminum.com
公司名称	铝合金精密加工有限公司
公司地址	深圳市宝安区西乡街道
邮编	518102
开户银行	工商银行
账号	1234567890123456
联系人	张经理
手机	13800138000
QQ	123456789
微信	aluminum2024
认证	ISO 9001
其他	
1. 铝合金CNC加工	
2. 精密加工	
3. 材料 AL6061 AL6065 AL6063 AL7075	
4. 表面处理	
5. 公差 ±0.01mm	
6. 数量 10000件	
7. 交货期	
8. 包装 25-30件	
9. 付款方式	
10. 工厂地址	
11. 认证 ISO 9001	
其他	
1.10 铝合金ISO	
2. 精密加工	
3. 表面处理	
4. 数量	
5. 公差	
6. 包装	
7. 交货期	
其他	
铝合金精密加工有限公司	
深圳市宝安区	
0755-12345678	
sales@aluminum.com	
ISO9001	
13800138000	
123456789	
OEM	