

Inspection Report

Report No.: XYFA-140915
Supplier : XY-GLOBAL

Inspection Date: 15th Oct-, 2014
Inspector: LEO

Inspection only for: PO . XYFA-140915 Item No. XY21ZC071	Inspection Result: PASS
--	--

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY21ZC071	6000pcs	7% inspection	0pcs	No failure	6000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Inspection report:

材料	铝合金CNC加工零件CNC
规格	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
用途	工业零件
精度	±0.01mm
公差	±0.01mm
表面处理	阳极氧化 喷砂 抛光
最小起订量	1000件
交货期	5-10天
包装	气泡膜+木箱
认证	ISO 9001
其他	

1. 材料	铝合金CNC
2. 规格	AL6061 AL6065 AL6063 AL7075
3. 用途	工业零件
4. 精度	±0.01mm
5. 公差	±0.01mm
6. 表面处理	阳极氧化
7. 最小起订量	1000件
8. 交货期	5-10天
9. 包装	气泡膜+木箱
10. 认证	ISO 9001
11. 其他	

材料	铝合金CNC
规格	AL6061 AL6065 AL6063 AL7075
用途	工业零件
精度	±0.01mm
公差	±0.01mm
表面处理	阳极氧化 喷砂 抛光
最小起订量	1000件
交货期	5-10天
包装	气泡膜+木箱
认证	ISO 9001
其他	

Safety is our serious job for our worker and engineer team

