

Inspection Report









Report No.: XYI-140320
Supplier : XY-GLOBAL

Inspection Date: 17th- Apr, 2014
Inspector: Leo

Inspection only for: PO . XYI-140320 Item No.142089	Inspection Result: PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
142089	40000PCS	1% inspection	0pcs	No failure	40000pcs

Appearance Inspection : No failure.
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:
	
7. Product:	8. Report:

品名	加工機用部品OEM部品
品番	ADC12 A380
仕様	
材質	アルミニウム
加工	切削加工
公差	CNC加工
表面処理	gague
寸法	
公差	+/-0.01
公差	T / T 50 T / T 50
公差	
公差	
公差	
公差	T / T 50 20-25 NBSP
公差	
1.Name	
2.Process	
	ADC12 A380
4.	
5.Tolerance	±0.01
6.	100
7.Specification	serice
8.	25-30
9.	accessoried
10.	Austrial
11&NBSP;	ISO 9001
1.	10 ISO
2.	
3.	kindls available
4.	
5.	
6.	
7.	
	NBSP;
	ISO9001
	OEM