

□□□□A356□□□□

Inspection Report

Report No.: XYS-130914
Supplier : XY-GLOBAL







Inspection Date: 11th Oct, 2013
Inspector: Leo

Inspection only for: PO . XYS-130920 Item No.3567200	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
3567200	3000PCS	5% inspection	0pcs	No failure	3000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. Product:

