

Inspection Report

Report No.: XYK-130821
 Supplier : XY-GLOBAL




Inspection Date:11th Sep-, 2013
 Inspector:Alex

Inspection only for: PO . XYK-130821	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
130014	1000PCS	3% inspection	0pcs	No failure	5000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product:

製品名	CNC加工機用CNC
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
用途	
仕様	
精度	
表面処理	
公差	
検査	
納期	
価格	
お問い合わせ	
お問い合わせ先	+/-0.01
お問い合わせ先	50
お問い合わせ先	
お問い合わせ先	
お問い合わせ先	
お問い合わせ先	
お問い合わせ先	50
お問い合わせ先	25
お問い合わせ先	
1. CNC加工機	
2. CNC加工機	
3. CNC加工機用CNC	AL6061 AL6065 AL6063 AL7075
4. CNC加工機用CNC	
5. CNC加工機用CNC	+/-0.01
6. CNC加工機用CNC	100
7. CNC加工機用CNC	
8. CNC加工機用CNC	25-30
9. CNC加工機用CNC	
10. CNC加工機用CNC	
11. CNC加工機用ISO 9001	
お問い合わせ先	
1.10 CNC加工機用ISO	
2. CNC加工機用CNC	
3. CNC加工機用CNC	
4. CNC加工機用CNC	
5. CNC加工機用CNC	
6. CNC加工機用CNC	
7. CNC加工機用CNC	
お問い合わせ先	
お問い合わせ先	
お問い合わせ先	
お問い合わせ先	ISO9001
お問い合わせ先	
お問い合わせ先	OEM