

Inspection Report

Report No.: XYFD-130804
Supplier : XY-GLOBAL

Inspection Date: 3th Sep-, 2013
Inspector: LEO

Inspection only for: PO . XYFD-130804 Item No.400-10-071	<u>Inspection Result:</u> PASS
--	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
400-10-071	6000Set	100% inspection	0pcs	No failure	6000Set

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :	
	
1. Packing	2. Product:
	
3. Product:	4. Product:
	
5. Product :	6. Product :

品名	CNC加工品CNC加工品
材質	AL6061 AL6065 AL6063 AL7075 SUS304 SUS303 SUS316
形状	形状
寸法	寸法
公差	公差
表面処理	表面処理
検査方法	検査方法
検査項目	検査項目
検査結果	検査結果
公差	公差
公差	+/-0.01
公差	公差50公差50
公差	公差
公差	公差
公差	公差50公差25
公差	公差
1. CNC加工	
2. 形状	
AL6061 AL6065 AL6063 AL7075	
4. 公差	
5. 公差±0.01	
6. 公差100	
7. 公差	
8. 公差25-30	
9. 公差	
10. 公差	
11. ISO 9001	
公差	
1.10. ISO	
2. 公差	
3. 公差	
4. 公差	
5. 公差	
6. 公差	
7. 公差	
公差	
公差	
公差	
公差ISO9001	
公差	
OEM	