

Inspection Report

Report No.: XYSL-150714
 Supplier : XY-GLOBAL






Inspection Date: 19th Aug, 2015
 Inspector: Leo

Inspection only for: PO . XYSL-150714 Item No. XY31XL034	Inspection Result: PASS
---	-----------------------------------

Description	Finished Q'ty	Sample Size	Defect Found	Defects Description	Acceptable Q'ty
XY31XL034	10000PCS	1% inspection	Opcs	No failure	10000pcs

Appearance Inspection : No failure,
Dimension Inspection: No failure , below measurement report for reference.
Assembly Test: No failure
Inspection Summary The inspection sample plan is 100% inspection.

Digital photo records :

	
1. Packing	2. Product
	
3. Product	4 Product
	
5. Product:	6. report

0000	0000000CNC00000000000000CNC00
00	000 AL6061 AL60650AL60630AL70750SUS3040SUS3030SUS3160
00	00000000
0000	00000000000000000000000000
00	0000000000
0000	00000000000000000000000000000000 0000
0000	00
000000	00000000
00/00	+/-0.0100
0000	00000500000000000000000005000000
0000	00
00	00
00	000000
00	000000050000000250000
0000	00000000
1.0000000000CNC00	
2.000000000000000000	
0000000AL6061 AL60650AL60630AL70750	
4.00000000000000000000 00000	
5.0000000±0.0100	
6.000000100000	
7.00000000000000000000000000	
8.00000025-3000	
9.0000000000000000000000 0000000000000000000000	
10.000000000000000000000000	
11000000000ISO 9001	
000000	
1.10000000ISO00	
2.000000000000000000	
3.000000000000000000	
4.000000000000	
5.000000	
6.000000	
7.00000000000000	
000000	
000000000000000000000000	
0000000000000000	
00000000000ISO9001	
00000000000000000000	
00OEM00000000	

Safety is our serious job for our worker and engineer team

